Riley County Environmental Health 110 Courthouse Plaza Manhattan, KS 66502 (785) 537-6332



Date: 8/7/2017 Number of Pupils: 500

e-mail: Jgranberry@usd378.org

## ANNUAL SCHOOL ENVIRONMENTAL / SANITATION INSPECTION REPORT

,	, and the second		
School Name: Riley Elementary School	Address: 5021 Orchard Street		
Inspected by: Steven DeHart REHS			
Received by: Teresa Grant			
·			
		COMPLIANC YES	
EXTERIORS:			NO
01 Exterior areas & surfaces: clean, good repair, debris, graded, no poo	oling water, illuminated	X	
02 Exterior structures: good repair, clean		X	
03 Playgrounds: equipment clean, good repair, ground cover (6"), storage, lighting		Х	
04 Refuse Containers: area clean, pests, odors, capacity, number, frequency, lids, solid surfaces		Х	
*05 Outdoor vector control: harborage conditions;		Х	
Exterior doors: tight fitting, good repair			
Windows/doors that open for ventilation: screening (#16 mesh), tight fitting, good repair			
06 Exterior Storage: machinery, maintenance items		Х	<u> </u>
INSECT & RODENT CONTROL:			
*07 No Presence of insects/rodents		X	
ELECTRICALSYSTEMS/LIGHTING:			
*08 Installed, maintained according to code: ground - fault circuit inte	rrunters within 5 ft of water source		Х
switch outlet covered, breaker boxes: protected, good condition, v			^
bare/frayed wiring: prohibited, 3 prong outlets grounded	The spiness covered,		
*09 Emergency lighting: adequate, good condition		Х	
10 Lighting: adequate (>30FC classroom), (>100FC lab or shop), shield	ing present light hulbs/fixtures	X	
PLUMBING/WATER/SEWAGE:	ing present, light builds/ lixtures		
11 Installed, maintained according to code		Х	
*12 Backflow, cross-connection: present, tested annually		NA NA	
*13 Source: safe, capacity, hot and cold water under pressure, tempe	rature	X	
*14 Sewage and waste water disposal		X	
15 Boiler inspection current		NA NA	
BATHROOMS:		I IVA	
16 Walls, ceiling, vents, floor: clean, good repair		Х	
17 Hand sink: adequate, clean, good repair		X	
*18 Toilet bowl, seat: clean, sanitized, good repair (1:50 toilets& 1:35	urinals boys) (1:35 toilets girls)	X	
19 Soap, towels, toilet tissue, toiletry items: provided, replenished as		X	
*20 Showers: clean, sanitized, good repair	,	NA	
TOXIC ITEMS:			
*21 Properly used, stored, labeled		Х	
PUBLIC INDOOR AREAS:			
22 Temperatures regulated (68 F to 74 F Winter), (74 F to 89 F Summe	er)	Х	
23 Structural Integrity; good repair, designed, disaster remediation	·	Х	
24 Ceilings & Floors: good repair, designed, clean		Х	
Additional Comments: <u>Install ground fault next to the sinks.</u>			

Riley County Environmental Health 110 Courthouse Plaza Manhattan, KS 66502 (785) 537-6332



Date: 8/7/2017 Number of Pupils: 225

e-mail: holiver@usd378

ANNUAL SCHOOL ENVIRONIVIENTAL /	SANITATION INSPECTION REPORT		
School Name: Riley County High School	Address: 12451 Fairview Church		
Inspected by: Steven De Hart REHS			
Received by: Harold Oliver		-	
neceived by. Harold Oliver			
		COMPLIANC	E STATUS:
EXTERIORS:		YES	NO
01 Exterior areas & surfaces: clean, good repair, debris, graded, no po	oling water, illuminated	Х	
02 Exterior structures: good repair, clean		Х	
03 Playgrounds: equipment clean, good repair, ground cover (6"), storage, lighting		NA	
04 Refuse Containers: area clean, pests, odors, capacity, number, frequency, lids, solid surfaces		Х	
*05 Outdoor vector control: harborage conditions;			
Exterior doors: tight fitting, good repair		X	
Windows/doors that open for ventilation: screening (#16 mesh),	tight fitting, good repair		
06 Exterior Storage: machinery, maintenance items		X	
INSECT & RODENT CONTROL:			
*07 No Presence of insects/rodents		X	
ELECTRICAL SYSTEMS/LIGHTING:	amustana within E ft of water course		
*08 Installed, maintained according to code: ground - fault circuit into switch outlet covered, breaker boxes: protected, good condition,		X	
bare/frayed wiring: prohibited, 3 prong outlets grounded	wife splices covered,	^	
*09 Emergency lighting: adequate, good condition		X	
	dia a a a a a a a a di a ba ba a ba a ba	X	
10 Lighting: adequate (> 30FC classroom), (>100FC lab or shop), shield	aing present, light bulbs/fixtures	^	
PLUMBING/WATER/SEWAGE:			
11 Installed, maintained according to code		X	
*12 Backflow, cross-connection: present, tested annually		NA	
*13 Source: safe, capacity, hot and cold water under pressure, temperature		X	
*14 Sewage and waste water disposal  15 Boiler inspection current			
BATHROOMS:		NA	<u> </u>
16 Walls, ceiling, vents, floor: clean, good repair		Х	
17 Hand sink: adequate, clean, good repair		X	
*18 Toilet bowl, seat: clean, sanitized, good repair (1:50 toilets& 1:35	urinals boys) (1:35 toilets girls)	X	
19 Soap, towels, toilet tissue, toiletry items: provided, replenished as			
*20 Showers: clean, sanitized, good repair	TIECESSAI Y	X NA	
TOXICITEMS:		IVA	
*21 Properly used, stored, labeled		Х	
PUBLIC INDOOR AREAS:			
22 Temperatures regulated (68 F to 74 F Winter), (74 F to 89 F Summ	er)	Х	
23 Structural Integrity; good repair, designed, disaster remediation		X	
24 Ceilings & Floors: good repair, designed, clean		X	
Additional Comments:			
		,	